

ADA Compliance Program

Clark County Facilities Transition Plan Public Service Center

Date of Survey: May 9, 2006

Conducted by: Wayne Yarnall Jesse Magana Teresa Guise Tim McVicker



Issue: Maneuvering Clearances at Manual Swinging Doors

ANSI Table 404.2.3.1 On the approach direction from front pull manual swinging doors there must be 18 inches of clear space parallel to the doorway (beyond the latch)

The following restroom doors do not meet this requirement. The required space on all doors is obstructed by the waste containers. Most doors measure 14 inches of clearance.

1st Floor Women's Restroom in Lobby

2nd Floor Women's and Men's Restroom in Lobby

3rd Floor Women's and Men's Restroom in Lobby

4th Floor Women's and Men's Restroom in Lobby

5th Floor Women's and Men's Restroom in Lobby

Recommendation

Move trash containers to a distance of 18 inches from the door frame.

Issue: Automatic Door



 Though not required, it is recommended that an automatic door be installed on the first floor east end lobby. The exterior door is automatic but the second door at the foot of the stairwell is not.



Issue: Emergency Intercoms in Evacuation Refuge Areas – No operation instruction in Braille.

ANSI 703.4.4 Position - Braille shall be below the corresponding text.

Recommendation:

Acquire signs for operation of intercom in Braille.



ADA Compliance Program



Issue: No operation instruction in Braille for ATM machine on second floor

ANSI 703.4.4 Position - Braille shall be below the corresponding text.

Recommendation

Acquire signs for operation of ATM in Braille.